## FBD Partnership, LP




P.O. BOX 18597 • SAN ANTONIO, TX 78218 USA •
210-637-2800 • FAX 210-637-2844 • www.fbdfrozen.com •
FBD TECHNICAL SUPPORT • 1-866-323-2777 •
TECHNICAL SUPPORT FAX 1-210-637-2832 •

## Service Bulletin 20-007 Rev 01 05/15/2020

## **New FBD Thermistor**

As part of FBD's continuous innovation process, FBD is introducing new thermistors for the 35x, 37x and 77X models. The change in thermistors being added to new dispensers only applies to those manufactured in the San Antonio facility at this time and changes of these at the Shenzhen facility will be implemented in the days that follow. The FBD part numbers for these components will change:



The new thermistor is a drop-in replacement and was implemented into dispensers in the San Antonio facility in May 15, 2020 starting with serial number 20050230.

|         |        | Old Thermistor |              |      |  |
|---------|--------|----------------|--------------|------|--|
| 352,    | 372    | 1/2"           | 70-0291-0003 | 1/2" |  |
| 353, 37 | 3, 77X | 5/8"           | 70-0291-0004 | 5/8" |  |

| New Thermistor |              |  |  |
|----------------|--------------|--|--|
| 1/2"           | 12-2602-0003 |  |  |
| 5/8"           | 12-2602-0002 |  |  |

For additional questions, please contact FBD Technical Support.

FBD TECHNICAL SUPPORT: 866-323-2777 (U.S.) or www.fbdfrozen.com